

WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

Section 1. Identification of the substance/mixture and of the company/undertaking

1.1 Product identifier **Product Form Trade Name** Product Code Use

Mixture WHITE AWAY EX WAEX

1.2 Relevant identified uses of the substance or mixture and uses advised against Industrial. For professional use only.

1.2.2 Uses Advised Against

No additional information available

1.3 Details of the supplier of the safety data sheet

Manufacturer

NOX-CRETE, INC. 1444 SOUTH 20TH STREET **OMAHA, NE 68108** Tel: 402-341-2080 Fax: 402-341-9752 E-Mail: corporate@nox-crete.com Web Site: www.nox-crete.com

1.4 Emergency telephone number

Emergency Number

Chemtrec (800) 424-9300 Chemtrec Outside of U.S. 703-527-3887

Section 2. **Hazards identification**

Classification of the substance or mixture 2.1

Flam Liq. 3	H226
Asp. Tox. 1	H304
Skin Irrit. 2	H315
Eye Irrit. 2	H319
STOT SE 3 resp. irrit.	H335
STOT SE 3 drowsiness	H336
Carc. 2	H351

Full text of H phrases see section 16 Adverse physiochemical, human health and environmental effects No additional information available

2.2 Label elements Hazard pictograms



Signal word

Danger

Hazard statements

H226 - Flammable liquid and vapor



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

Precautionary statements	H304 - May be fatal if swallowed and enters airways H315 - Causes skin irritation H319 - Causes serious eye irritation H335 - May cause respiratory irritation H336 - May cause drowsiness or dizziness H351- Suspected of causing cancer
Prevention:	 P201- Obtain special instructions before use. P202- Do not handle until all safety precautions have been read and understood. P210: Keep away from heat/sparks/open flames/hot surfaces-No smoking. P233- Keep container tightly closed P240 - Ground/bond container and receiving equipment P241 - Use explosion-proof electrical/ventilating/light//equipment P242 - Use only non-sparking tools P243 - Take precautionary measures against static discharge P260 - Do not breathe dust/fume/gas/mist/vapors/spray P264 - Wash exposed area's thoroughly after handling. P271 - Use only outdoors or in a well-ventilated area. P280 - Wear protective gloves/protective clothing/eye protection/face protection P281- Use personal protective equipment as required
Response:	 P301+P310 - IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician P303+P361+P353: IF ON SKIN (or hair): Remove / Take off immediately all contaminated clothing. Rinse skin with water / shower P304+P340 - IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. P305+P351+P338 -IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do so - continue rinsing P308+P313 - IF exposed or concerned: Get medical advice/attention P312 - Call a POISON CENTER or doctor/physician if you feel unwell. P331 - Do NOT induce vomiting P332+P313 - If skin irritation occurs: Get medical advice/attention P337+P313 - If eye irritation persists: Get medical advice/attention P362 - Take off contaminated clothing and wash before reuse. P370+P378 - In case of fire: Use Dry chemical, foam, carbon dioxide for extinction
Storage:	P405+P403+P235 - Store locked up in a well-ventilated place. Keep cool.
Disposal:	P501: Dispose of contents/container in accordance with local/regional/national/international regulations.

Full text of H and P phrases: see section 16



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

2.3 Other hazards

None known

Section 3. Composition / information on ingredients

3.1 Substances

Not applicable

3.2 Mixture

Name	Product identifier	%
Exempt Solvent	Trade Secret	Trade Secret
Organic Solvent	Trade Secret	Trade Secret
Ethylbenzene	100-41-4	< 0.5
1,2,4-trimethylbenzene	95-63-6	< 13.0
Xylene	1330-20-7	< 3.0
Cumene	98-82-8	< 3.0

Pursuant to 29CFR 1910.1200(i) the specific chemical identity (and / or) concentration may be withheld as Trade Secret, while all health and safety properties and effects are included in the SDS. Balance of other ingredients are non-hazardous or less than 1% in concentration (or 0.1% for carcinogens, reproductive toxins, or respiratory sensitizers).

Section 4. First aid measures

4.1 Description of first aid measures	
First-aid measures general	Get medical advice/attention if you feel unwell. Never give anything by
	mouth to an unconscious person.
First-aid measures after inhalation	If the individual experiences nausea, dizziness, has difficulty in
	breathing seek a healthcare professional immediately. In all cases of
	doubt, or when symptoms persist, seek medical advice. Remove to
	fresh air and keep at rest in a position comfortable for breathing.
	Immediately call a Poison Center or doctor/physician.
First-aid measures after skin contact	If skin irritation persists, seek medical attention. Remove or take off
	immediately all contaminated clothing. Rinse skin with water or shower.
	Wash off immediately with soap and plenty of water.
First-aid measure after eye contact	When contact lenses are worn, remove if possible. In case of contact
	with eyes, rinse immediately with plenty of flowing water for 10 to 15
	minutes while holding eyelids apart. Get medical attention immediately.
First-aid measures after ingestion	Rinse mouth. DO NOT induce vomiting. Get medical attention
	immediately.
4.2 Most important symptoms and effect	s, acute and delayed
Symptoms/injuries after inhalation	May cause irritation to the respiratory tract. Overexposure to vapors may
	result in headache, nausea, drowsiness or dizziness.
Symptoms/injuries after skin contact	May cause skin irritation or burning sensation
Symptoms/injuries after eye contact	May cause eye irritation or injury
Symptoms/injuries after ingestion	May cause severe irritation or burns to the mucous membrane of the
	mouth, throat, esophagus and stomach
4.0 In the other of any linear a the second start	ette autoral en la casa del tra etterrent a casa la l

4.3 Indication of any immediate medical attention and special treatment needed



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

No additional information available

Section 5. Firefighting measures	
Suitable extinguishing media	Dry chemical, toam, carbon dioxide
Unsuitable extinguishing media	Do not use heavy water stream
5.2 Special hazards arising from the subst	
Reactivity	Thermal decomposition products may cause a health hazard.
5.3 Advice for firefighters	
Firefighting instructions	Flammable Liquid! This material releases vapors when heated above
r nenghang instructions	ambient temperatures. Vapors can cause a flash fire. Use water spray
	or fog to cool exposed containers.
Drotootive on viewort for fireficktore	•
Protective equipment for firefighters	Firefighters should always wear self-contained breathing apparatus
	(SCBA) and full protective gear when fighting any chemical fire.
Other information	On heating or burning harmful gasses/vapors may be released.
	This product may cause the floor to become slippery.
Section 6. Accidental release measure	ires
6.1 Personal precautions, protective equip	ment and emergency procedures
General measures	Extremely Flammable. Eliminate any ignition sources. Dike or impound
	spilled material. Use Non-sparking tools. All equipment must be
	grounded. Take proper precautions to ensure your own health and
	safety before attempting spill control or cleanup.
6.11 Protective Equipment	Equip cleanup crew with proper protective equipment.
6.2 Environmental precautions	Prevent entry to sewers and public waters.
0.2 Environmental precautions	
C.O. Matheda and materials for containment	Notify authorities if liquid enters sewers or public waters.
6.3 Methods and materials for containmen	
Methods for cleaning up	Soak up spills with inert solids, such as clay or diatomaceous earth.
	Collect into vapor tight containers and dispose of properly.
Section 7. Handling and storage	
7.1 Precautions for safe handling	
7.1 Precautions for safe handling Protective measures	Wash hands and other exposed areas with soap and water before
	eating, drinking or smoking and when leaving work. Provide good
	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use
	eating, drinking or smoking and when leaving work. Provide good
	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use
Protective measures Hygiene measures	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse.
Protective measures Hygiene measures 7.2 Conditions for safe storage, including	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. any incompatibilities
Protective measures Hygiene measures	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. <u>any incompatibilities</u> Store in accordance with local regulations. Store in original container in
Protective measures Hygiene measures 7.2 Conditions for safe storage, including	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. <u>any incompatibilities</u> Store in accordance with local regulations. Store in original container in a cool well-ventilated place away from heat, sparks and open flame.
Protective measures Hygiene measures <u>7.2 Conditions for safe storage, including</u> Storage conditions	 eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. any incompatibilities Store in accordance with local regulations. Store in original container in a cool well-ventilated place away from heat, sparks and open flame. Keep containers tightly closed until ready for use.
Protective measures Hygiene measures <u>7.2 Conditions for safe storage, including</u> Storage conditions	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. any incompatibilities Store in accordance with local regulations. Store in original container in a cool well-ventilated place away from heat, sparks and open flame. Keep containers tightly closed until ready for use. Strong oxidizing agents and acids
Protective measures Hygiene measures <u>7.2 Conditions for safe storage, including</u> Storage conditions	 eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. any incompatibilities Store in accordance with local regulations. Store in original container in a cool well-ventilated place away from heat, sparks and open flame. Keep containers tightly closed until ready for use.
Protective measures Hygiene measures <u>7.2 Conditions for safe storage, including</u> Storage conditions Incompatible materials Storage temperature	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. <u>any incompatibilities</u> Store in accordance with local regulations. Store in original container in a cool well-ventilated place away from heat, sparks and open flame. Keep containers tightly closed until ready for use. Strong oxidizing agents and acids Store in a cool dry environment away from sources of ignition.
Protective measures Hygiene measures <u>7.2 Conditions for safe storage, including</u> Storage conditions	eating, drinking or smoking and when leaving work. Provide good ventilation in work areas to prevent formation of vapor. When not in use keep containers tightly closed. Avoid breathing vapor or mist. Wash contaminated clothing before reuse. <u>any incompatibilities</u> Store in accordance with local regulations. Store in original container in a cool well-ventilated place away from heat, sparks and open flame. Keep containers tightly closed until ready for use. Strong oxidizing agents and acids Store in a cool dry environment away from sources of ignition.

8.1 Control parameters

Occupational exposure limits

Ingredient name	Occupational exposure limits ACGIH TLV (United States)
Organic Solvent	TWA: 100 g/m3 8 hours



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

Xylene	TWA: 100 ppm 8 hours
1,2,4-trimethylbenzene	TWA: 25 ppm 8 hours
Ethylbenzene	TWA: 20 ppm 8 hours
Cumene	TWA: 50 ppm 8 hours
8.2 Exposure controls	
Appropriate engineering controls	Use with adequate ventilation to keep product vapor concentrations below specified TLV
Eye and face protection	Chemical goggles and/or face shields are recommended to prevent potential eye contact, irritation or injury.
Skin protection	Wear chemical resistant gloves and appropriate protective clothing and boots as required to prevent skin contact. Wash exposed skin frequently with soap and water. Soiled clothing should be laundered before reuse.
Respiratory protection	General room ventilation is normally adequate. Avoid breathing the product mist or vapors. The use of an appropriate respirator is recommended whenever the airborne concentrations exceed the TLV.

Section 9. Physical and chemical properties

Information on basic physical and chemical properties 9.1

Appearance	Clear liquid
Odor	Sweet
Odor Threshold	No data available
PH	No data available
Melting point	No data available
Freezing point	No data available
Boiling point	> 138 C (>280 F)
Flash point	> 43 C >109 F PMCC
Relative evaporation rate (butyl acetate=1)	No data available
Flammability (solid, gas)	No data available
Upper/lower explosive limits	No data available
Vapor pressure	No data available
Vapor density	No data available
Relative density (Specific gravity)	1.054 Kg per Liter 8.8 Lbs per Gallon
Solubility	Water: Negligible
Partition coefficient n-octanol/water	No data available
Auto-ignition temperature	Not applicable
Viscosity	No data available
VOC content	No data available

Section 10. Stability and reactivity

10.1 Reactivity

<u>10.1</u>	Reactivity	No additional information available
<u>10.2</u>	Chemical stability	Stable under normal conditions
<u>10.3</u>	Possibility of hazardous reactions	Hazardous polymerization will not occur.
<u>10.4</u>	Conditions to avoid	Extreme high or low temperatures.
<u>10.5</u>	Incompatible materials	Strong acids and oxidizers
10.6	Hazardous decomposition products	carbon monoxide, carbon dioxide, various hydrocarbon derivatives

Section 11. Toxicology information



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

11.1 Information on toxicological effects Acute toxicity

Irritation/Corrosion Skin Eyes

Respiration or skin sensitization Germ cell mutagenicity Carcinogenicity IARC

Xylene	3
Ethylbenzene	2B
Cumene	2B

No adverse effects expected under intended use. May cause skin irritation May cause serious eye irritation and damage. May cause respiratory irritation No data available

2B - Limited evidence in humans and less than sufficient evidence in animals.

3 - Inadequate in humans and inadequate or limited in animals.

Reproductive toxicity	No data available
Specific target organ toxicity	
Single exposure	No data available
Repeated exposure	No data available
Aspiration hazard	May be fatal if swallowed and enters airways

Section 12. Ecological information	
12.1 Ecotoxicity	Not established
12.2 Persistence and degradability	Not established
12.3 Bioaccumulative potential	Not established
12.4 Mobility in soil	No additional information available
12.5 Other adverse effects	Avoid release to the environment

SECTION 13. Disposal Considerations

13.1 Waste treatment methods

The user of this material has the responsibility to dispose of unused material, residues and containers in compliance with all applicable local, state and federal laws and regulations regarding treatment, storage and disposal for hazardous and nonhazardous wastes.

SECTION 14. Transport information

In accordance with US DOT

Not regulated under 119 US gallons.

In accordance with ADR / RID / ADNR / IMDG / ICAO / IATA	
1263	
Paint Related Material	
3	
III	
No additional information available	
No additional information available	



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

14.8 Transport in bulk according to CFR 49 173.15 Not applicable SECTION 15. **Regulatory** information 15.1 Safety, health and environmental regulations/legislation specific for the substance or mixture 15.1.2 USA Regulations Section 313 Contains the following ingredients at or above the reporting level requirements of Section 313. This information must be included in all SDS's copied or distributed for this material. MAX WEIGHT % **CHEMICAL** CAS # **Xvlene** 1330-20-7 3.0 1,2,4-Trimethylbenzene 95-63-6 13 3.0 Cumene 98-82-8 Ethylbenzene 100-41-4 0.5 **TSCA** All ingredients are listed or exempted **PROPOSITION 65** WARNING: NOT FOR SALE IN CALIFORNIA 15.1.3 Canada Regulations This SDS has been prepared according to the hazard criteria of the Hazardous Products Regulation (HPR) (WHMIS 2015) and the SDS contains all of the information required by the HPR. All ingredients are listed or exempted DSL A Chemical Safety Assessment has not been carried out. 15.2 Chemical safety assessment Section 16. Other information Date of issue / revision 9-29-2023 Version 2.0 Number 1019 Date of previous issue / revision Preparer Nox-Crete, Inc. **Reference Documentation**

The information and recommendations contained herein are, to the best of Nox-Crete, Inc.'s knowledge and belief, accurate and reliable as of the date issued. You can contact Nox-Crete, Inc. to ensure that this document is the most current available from Nox-Crete, Inc. The information and recommendations are offered for the buyer's/user's consideration and examination. It is the buyer's/user's responsibility to satisfy themselves that the product is suitable for the intended use. Appropriate warnings and safe-handling procedures should be provided to all handlers and users. Since conditions for use of the product are not under the control of the manufacturer, it is the buyer's/user's duty to determine the conditions necessary for the safe use of this product. Since the information provided herein may have been obtained in part from independent laboratories or other sources not under our direct supervision, no representation is made that the information is accurate, reliable, complete or representative and buyer/user may rely thereon only at their risk. We have made no effort to censor or to conceal deleterious aspects of this product. Further, since we cannot anticipate or control the many different conditions under which this information or our products may be used, we make no guarantee that the health and/or safety precautions we have suggested will be adequate for all individuals and /or situations involving its handling or use. Likewise, we make no guarantee or warranty of any kind that the use or disposal of this product is in compliance with all federal, state or local laws. It is the obligation of each buyer/user of the product mentioned herein to determine and comply with the requirements of all applicable statutes. If buyer/user repackages this product, it is the buyer's/user's responsibility to ensure proper health, safety and other necessary information is included with and/or on the



WHITE AWAY EX

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

container. Nox-Crete, Inc. urges each customer or recipient of this SDS to study it carefully and consult appropriate expertise, as necessary or appropriate, to become aware of and understand the data contained in this SDS and any hazards associated with this product. Alteration of this document is strictly prohibited. Except to the extent required by law, re-publication or retransmission of this document, in whole or in part is not permitted.

Full text of H and P phrases

H226
H304
H315
H319
H335
H336
H351

- H226 Flammable liquid and vapor
- H304 May be fatal if swallowed and enters airways
- H315 Causes skin irritation
- H319 Causes serious eye irritation
- H335 May cause respiratory irritation
- H336 May cause drowsiness or dizziness
- H351- Suspected of causing cancer
- P201- Obtain special instructions before use.
- P202- Do not handle until all safety precautions have been read and understood.
- P210: Keep away from heat/sparks/open flames/hot surfaces-No smoking.
- P233- Keep container tightly closed
- P240 Ground/bond container and receiving equipment
- P241 Use explosion-proof electrical/ventilating/light/.../equipment
- P242 Use only non-sparking tools
- P243 Take precautionary measures against static discharge
- P260 Do not breathe dust/fume/gas/mist/vapors/spray
- P264 Wash exposed area's thoroughly after handling.
- P271 Use only outdoors or in a well-ventilated area.
- P280 Wear protective gloves/protective clothing/eye protection/face protection
- P301+P310 IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician
- P303+P361+P353: IF ON SKIN (or hair): Remove / Take off immediately all contaminated clothing. Rinse skin with water / shower
- P304+P340 IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.
- P305+P351+P338 -IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do so continue rinsing
- P308+P313 IF exposed or concerned: Get medical advice/attention
- P312 Call a POISON CENTER or doctor/physician if you feel unwell.
- P331 Do NOT induce vomiting
- P332+P313 If skin irritation occurs: Get medical advice/attention
- P337+P313 If eye irritation persists: Get medical advice/attention
- P362 Take off contaminated clothing and wash before reuse.
- P370+P378 In case of fire: Use Dry chemical, foam, carbon dioxide for extinction.



WHITE AWAY EX

Safety Data Sheet

According to Regulation 29 CFR 1910.1200, Regulation (EC) No. 1272/2008 (CLP)(GHS), Hazardous Products Regulation (HPR) (WHMIS 2015

P405+P403+P235 - Store locked up in a well-ventilated place. Keep cool.

P501: Dispose of contents/container in accordance with local/regional/national/international regulations.